
REPORT ON NOISE MONITORING

AT

GRANGEGORMAN CAMPUS CENTRAL & EAST QUAD,

DUBLIN 7

INTERIM NOISE REPORT 05-01: 23rd March to 10th April 2018.

Prepared by:

Glenside Environmental
Unit 18 Great Island Industrial Estate
Ballincollig,
Cork

Prepared for:

Sisk FCC GG PPP Joint Venture
Wilton Works
Naas Road
Clondalkin
Dublin 22

TABLE OF CONTENTS

1.0	INTRODUCTION.....	3
2.0	NOISE MEASUREMENT SURVEY.....	3
3.0	RESULTS	3
4.0	CONCLUSIONS	3

1.0 INTRODUCTION

Glenside Environmental were commissioned by Sisk FCC GG PPP Joint Venture, to conduct noise monitoring during site development works at Grangegorman Campus Central & East Quad Dublin 7. This report presents the results of noise monitoring at 2 locations; Location A East Quad West Boundary Wall and Location B Grangegorman Upper, from 23rd March to 10th April 2018. The locations are illustrated on Figure 1.

2.0 Noise Measurement Survey

A continuous environmental noise monitoring survey was conducted by installing 2 no. data logging noise monitors at sensitive locations adjacent the works at the site. Location A at and location B is adjacent a residential property.


3.0 Results

Results of the noise monitoring are presented in Graphs 1 to 2 and the location of the monitoring positions are shown in Figure 1.


4.0 CONCLUSIONS

The graphs below specify the continuous noise levels at the monitoring locations A, B, during the reporting period 23rd March to 10th April 2018. Regular local traffic dominates the noise levels at Locations A at the East Quad West Boundary Wall and Location B at Grangegorman Upper adjacent the apartments at the east of the site.

Figure 1: Noise Monitoring Locations



Graph 1: Noise Levels at Location A East Quad West Boundary Wall from 23rd March to 10th April 2018.



Graph 2: Noise Levels at Location B Grangegorman Upper from 23rd March to 10th April 2018

